

PRIORITY ONE

Camera Repair Capabilities

** Priority One's repair capabilities include (but are not limited to) the makes/models listed.
Please call 800-548-5289 for all makes/models not listed.

Accufex (single chip)
Baxter AR6000 (single chip)
Baxter AR6500 (single chip)
Baxter 3000 (3-chip)
Baxter OPTX 1000 (single chip)
Cabot (All single chip)
Circon IV (MV-9690/MV-9692) (single chip)
Circon V (MV-9660/MV-9662) (single chip)
Circon 3-chip (MV-9906)
Circon MV-100XX (single chip)
Circon MV-105XX (3-chip)
Claris 5191 (single chip)
Concept 8100/8150/8160 (single chip)
Cooper LSS600 (single chip)
Dyonics 450/550/650/700/750 (single chip)
Dyonics Digital (single chip)
Dyonics D3 (3-chip)
Dyonics ED-3 (3-chip)
Dyonics HD-900 (single chip)
Dyonics 337 (3-chip)(autoclavable)
Dyonics 370 & 470 (3-chip)
Elmo (all single chip)
Envision (all single chip)
Javelin (all single chip)
Linvatec 8170/8171/8172 (single chip)
Linvatec 9011 (3-chip)
Linvatec C3181 (non-autoclavable) (single chip)
Linvatec C3114, C3284/5/6/7 (autoclavable) (single chip)
Linvatec C3136, C3138 (non-autoclavable)(3-chip)
Linvatec C3236, C3238, C3242 (autoclavable) (3-chip)
Linvatec IM332X & IM333X
Linvatec IM4000
MP Video (all single chip)
Olympus MC-6 (single chip)
Olympus OTV-S2 (single chip)
Olympus OTV-S4 (single chip)
Olympus OTV-S5 (single chip)
Olympus OTV-S5 w/ coupler (single chip)
Olympus OTV-S6 (single chip)
Olympus OTV-S6 w/ coupler (single chip)
Olympus OTV-S6 (single chip-autoclavable)

** Priority One is an independent Repair Service Provider and an authorized representative of Fujinon® USA, Inc. Priority One does not represent any other manufacturer.

Olympus OTV-S7 (single chip)
Olympus OTV-S7 w/ coupler (single chip)
Olympus OTV-S7 (single chip-autoclavable)
Olympus OTV-S7 3 CCD(single chip)
Olympus OTV-S7 1080P(single chip)
Olympus OTV-SX (3-chip)
Olympus OTV-SX2 (3-chip)
Olympus OTV-SX2 (3-chip)(autoclavable)
Olympus OVC-100/OVC-200
Olympus OBV-1 (single chip)
Olympus OTV-SE (single chip)
Olympus OTV-SC (single chip)
Olympus OTV-A (single chip)
Olympus Endoeye
Pentax Endovision 3000 (single chip)
Pentax IPX-7 (single chip)
Richards Vista Vision II (single chip)
Smith & Nephew 360 & 460 series (3-chip)
Smith & Nephew 560H (3-chip)
Solos GS9400S (single chip)
Solos GS9490S (single chip)
Solos GS9940S (3 chip)
Sony XC-711, CMA-D7, DXC750, DXC107
Storz 9050 (single chip)
Storz 9050B (single chip)
Storz 9070B (3-chip)
Storz Telecam 20210130/20212130 (single chip)
Storz Telecam 20212131/32 or 20210131/32 (single chip)
Storz Telecam 20212134 (single chip)
Storz Telecam 2021X14X (autoclavable)(single chip)
Storz Image 1 (single chip)
Storz Image 1 (autoclavable) (single chip)
Storz Tricam 20221140 (autoclavable)(3-chip)
Storz Tricam 2022113X (3-chip)
Storz Image 1 "S" series (3-chip)
Storz Image 1 "H" series (3-chip)
Storz Image 1 "A" series (3-chip)
Storz Image 1 "P" series (3-chip)
Stryker 570/572/578 (single chip)
Stryker 590/591/592/596 (single chip)
Stryker 596 (single chip) (autoclavable)
Stryker 688 (single chip)
Stryker 688 (autoclavable) (single chip)
Stryker 777/780/782 (3-chip)
Stryker 810/882TE (3-chip)
Stryker 888 (3-chip)
Stryker 988 (3-chip)

Stryker 988 (autoclavable) (3-chip)
Stryker 1088 (3-chip)
Stryker 1188 (3 chip)
Stryker 1188 (autoclavable) (3-chip)
Stryker 1288 (3 chip)
Wolf single chip camera
Wolf 5504 or 5506 (3-chip)
Wolf 5508
Wolf 5520
Zeiss 99459 (single chip)
Zeiss ZVS1470 (single chip)

COUPLERS/BEAMSPLITTERS

Most model couplers except below
Couplers with focus and zoom ring
Autoclavable couplers
Most minor mechanical repairs
Beamsplitters

CAMERA ADAPTORS (PIGTAILS)

MD-148 w/o cracked covers
MD-148 w/ cracked covers
MD-149 w/o cracked covers
MD-149 w/ cracked covers
MH-228 w/o cracked covers
MH-228 w/ cracked covers
MH-236 w/o cracked covers
MH-236 w/ cracked covers
MH-237 w/o cracked covers
MH-237 w/ cracked covers
MAJ-843 w/o cracked covers
MAJ-843 w/ cracked covers
MAJ-1430 w/o cracked covers
MAJ-1430 w/ cracked covers
MH-977 w/o cracked covers
MH-977 w/ cracked covers

CONSOLES

All Models except below
Olympus CV-100

LIGHT SOURCES

Xenon w/o power supply problems
Xenon w/ power supply problems
Xenon power supply replacement
HTI w/o power supply problems
HTI w/ power supply problem
HTI power supply replacement
Halogen w/o power supply problems
Halogen w/ power supply problems

VIDEO PRINTERS

All Sony/Olympus Models w/o thermal head replacement
All Sony/Olympus Models w/ thermal head replacement
All Toshiba/Stryker Models w/o thermal head replacement
All Toshiba/Stryker Models w/ thermal head replacement
All Models that need electronic board replacement